

Major repairs to Portsea beach seawall

Project Update - 27 March 2020

Repair works to the Portsea sandbag seawall are continuing.

Delivery of the new sandbags will now become a regular and daily event. Contractors are working from the eastern end of the sandbag seawall and will progressively move west towards the pier.

Improvements to the coastal path along the Crown foreshore land and the beach access steps opposite Norfolk Drive have been completed, including new signage to mark the path.

Pedestrian access to the pier is being maintained during works, and the temporary rock wall remains in place to protect workers.

Please respect the warning signs and keep out of the site, even after hours – this is for your own safety.

Erosion of the beach and cliffs immediately east of the sandbag seawall at Portsea has been identified to potentially pose a threat to the stability of the cliff. Specialists from Senversa have been engaged to undertake geotechnical investigations of these cliffs to understand any risks to the public, in addition to public and private land.

